# IN THE COURT APPEALS OF THE STATE OF NEVADA No. 81637-COA

### KEOLIS TRANSIT SERVICES, LLC Petitioner

Electronically Filed Nov 12 2020 09:43 a.m. Elizabeth A. Brown Clerk of Supreme Court

#### v. THE EIGHTH JUDICIAL DISTRICT COURT OF THE STATE OF NEVADA IN AND FOR THE COUNTY OF CLARK, AND THE HONORABLE RICHARD SCOTTI, DEPT. II,

Respondents

and

SHAY TOTH Real Party in Interest

#### SUPPLEMENTAL APPENDIX RE WRIT OF PROHIBITION

# **RESPONDENT'S APPENDIX**

Pages 0001-0005

CLIFF W. MARCEK, ESQ. Nevada Bar No. 5061 CLIFF W. MARCEK, P.C. 411 E. Bonneville, Suite 390 Las Vegas, Nevada 89101 Telephone (702) 366-7076 Facsimile (702) 366-7078

BOYD B. MOSS III, ESQ. Nevada Bar No. 8856 MOSS BERG INJURY LAWYERS 4101 Meadows Lane, Suite 110 Las Vegas, Nevada 89107 Telephone: (702) 222-4555 Facsimile: (702) 222-4556

Attorneys for Real Party in Interest SHAY TOTH

# **RESPONDENT'S APPENDIX**

Description

Bates number

1. Repair estimate on Plf's vehicle Respondent 0001-00005

## **ULTIMATE Collision Repair Center**

Uncompromising Dedication to Quality and Service 3291 North Rancho Drive, Las Vegas, NV 89130 Phone: (702) 949-2886 FAX: (702) 951-4635 Workfile ID: Federal ID: License Number: 47e0a1b2 800008102 BD0000025625

and a second second

#### Supplement of Record 4 with Summary **Customer: TOTH, FRANCIS Job Number:** Written By: Lee Andersen, 7/28/2017 9:36:34 AM Adjuster: WCZ, OYSAR, (877) 777-2022 Business Insured: TOTH, FRANCIS PPXM0057817700 516279-GF-2 Policy #: Claim #: Type of Loss: COLL - Collision 7/1/2017 5:20 PM Date of Loss: Days to Repair: 13 Point of Impact: 06 Rear **Owner: Inspection Location: Insurance Company:** DEPOSITORS INSURANCE COMPANY TOTH, FRANCIS 917 BONITA AVE NEVADA STATE OYSARN 6085 EGAN CREST DR LAS VEGAS, NV 89104 LAS VEGAS, NV 89149 Other One Nationwide Plaza NA-04-03 (702) 808-0317 Evening (702) 808-0317 Cell Columbus, OH 43215 VEHICLE 2015 TOYO Corolla LE w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI blueish gr VIN: 5YFBURHE1FP271987 Interior Color: Mileage In: 34,002 Vehicle Out: 7/21/2017

icense:	821ZAZ	Exterior Color: blueish gr	Mileage Out:	
tate:	NV	Production Date:	Condition:	Job #:
TR/	ANSMISSION	Air Conditioning	Search/Seek	Bucket Seats
Auto	omatic Transmission	Intermittent Wipers	CD Player	WHEELS
POI	WER	Tilt Wheel	Auxiliary Audio Connection	Wheel Covers
Pow	ver Steering	Cruise Control	Equalizer	PAINT
Pow	ver Brakes	Rear Defogger	SAFETY	Clear Coat Paint
Pow	ver Windows	Keyless Entry	Drivers Side Air Bag	OTHER
Pow	ver Locks	Steering Wheel Touch Controls	Passenger Air Bag	Fog Lamps
Pow	er Mirrors	Telescopic Wheel	Anti-Lock Brakes (4)	Traction Control
Hea	ted Mirrors	Climate Control	4 Wheel Disc Brakes	Stability Control
DEC	COR	Backup Camera w/Parking Sensors	Front Side Impact Air Bags	Rear Spoiler
Dua	I Mirrors	RADIO	Head/Curtain Air Bags	Signal Integrated Mirrors
Tinte	ed Glass	AM Radio	Hands Free Device	Xenon Headlamps
Cons	sole/Storage	FM Radio	SEATS	California Emissions
CON	VVENIENCE	Stereo	Cloth Seats	Power Trunk/Gate Release

### Supplement of Record 4 with Summary

# Customer: TOTH, FRANCIS

4

No. of the second

and the state of the second second

#### Job Number:

оор балбашык боло 7 ток өктөрсөн болболко төрөө соосоо

2015 TOYO Corolla LE w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI blueish gr

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Pain
1	#		Rpr	Pull & Square Rear Unibody		0	0.00	2.0 F	0.0
2	#			Set Up & Measure (Car-O-Liner Sheet)		1	0.00	2,0 F	0.0
3	REA	R BUM	PER	· · · · · · · · · · · · · · · · · · ·	· · · · · ·			• • • • • • • • • • • • • • • • • • • •	
4	**		Repl	A/M CAPA Impact bar	5217102230	1	168.00	0.3	0.0
5		S	)4	O/H rear bumper		0	0.00	1.6	0.0
6	** .	<> 5(	)4 Repl	A/M CAPA Bumper cover	5215903901	1	233.00	Incl.	2.6
7		S	)4	Add for Clear Coat		0	0.00	0.0	1.0
8	**		Repl	A/M AQRP RT Bumper bracket	5218102160	1	30.00	0.2	0.0
9	**		Repl	A/M AQRP LT Bumper bracket	5218202130	1	30,00	0.2	0.0
10		S	1 Repl	LT Side support	5257602110	1	60,48	0,1	0.0
11		SC	1 Repl	RT Side support	5257502110	1	60.48	0.1	0.0
12	**	SC	2 Repl	Opt OEM Step pad		1	70.00	0,2	0.0
13	REAF		S	* South And Stream Stream (2000) Said State (2000)	and the start start start and start		I is an integrated on an an observed state of the first state.		
14	*	SC	2 Repl	LKQ RT Combo lamp assy +25%	8155002751	1	75.00	0.3	0.0
				Note: LKQ part only ins quality at this prio	te				
15	**	SC	2 Repl	A/M AQRP LT Combo lamp assy	8156002751	i	97.00	0.3	0.0
				Note: LKQ not ins quality					
16	**		Repi	A/M AQRP RT Backup lamp assy	8158002510	1	74.00	Incl.	0.0
17	**		Repl	A/M AQRP LT Backup lamp assy	8159002510	1	74.00	Incl.	0.0
18			Repl	RT Combo lamp assy guide	8149660010	1	1.87	0.0	0.6
19			Repl	LT Combo lamp assy guide	8149660010	1	1.87	0.0	0,0
20	TRUM	IK LID							
21	**		Repl	Opt OEM Trunk lid w/spoiler w/Smart Key	6440102850	1	<u>346.64</u>	2.9	2.2
22		S0	4	Overlap Major Non-Adj. Panel		0	0.00	0.0	-0.2
23				Add for Clear Coat		0	0.00	0.0	0.4
24				Add for camera		0	0.00	0.2	0.0
25				Add for spoiler		0	0.00	0.4	0.0
26				Add for Underside(Complete)		0	0.00	0,0	1.1
27			Repl	Weatherstrip	6446102180	1	54.69	Incl.	0.0
28	*		Rpr	RT Hinge		0	0.00	<u>0.5</u>	<u>0.(</u>
29	**		Repl	Opt OEM Lock assy w/o Smart Key	6461002171	1	<u>40.00</u>	0.3	0.(
30			Repl	Nameplate "COROLLA"	7544202280	1	31.66	0.2	0.0
31			Repl	Emblem	90975A2003	1	33.27	0.1	0,0
32			Repl	Nameplate "LE"	7544412D20	1	24.68	0.2	0.0
33			Repl	Trim molding w/o camera	7582702040	1	30.43	Incl.	0.0
34	*		Rpr	LT Hinge		0	0.00	<u>0.5</u>	<u>0.0</u>
85			Repl	Lock assy w/Smart Key	6460002031	1	231.67	0.3	0.
36			Repl	Striker	6462102020	1	8.76	Incl.	0.0
37	#	S0:	L Rpr	Pre-fit trunk lid		0	0.00	0.5	0.0

Page 2

#### Supplement of Record 4 with Summary

#### **Customer: TOTH, FRANCIS**

#### Job Number:

2015 TOYO Corolla LE w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI blueish gr

39			Repl	Rear body panel	5830702350	1	466.08	6.8	1.6
40				Overlap Major Adj. Panel		0	0.00	0.0	-0.4
41				Add for Clear Coat		0	0.00	0.0	0.2
42				Add for Inside		0	0.00	0.0	0.8
43			R&I	RT Side trim panel		0	0.00	0.3	0.0
44			R&I	LT Side trim panel		0	0.00	0.3	0.0
45			Repl	Rear panel trim	5838702211	1	140.41	Inci.	0.0
46			Repi	Spare cover	6477102370C0	1	279.08	0.1	0.0
47	*		Rpr	Rear floor pan		0	0.00	<u>2.0</u>	1.5
48	*		Rpr	RT Rail end (HSS)		0	0.00 s	<u>1.0</u>	0.8
49				Overlap Minor Panel		0	0.00	0.0	-0.2
50	*		Rpr	LT Rail end (HSS)		0	0.00 s	2.0	0.8
51				Overlap Minor Panel		0	0.00	0.0	-0.2
52		S01	R&I	Pkg tray trim		0	0.00	Incl.	0.0
53	QUAR	RTER PA	NEL						
54			Repl	RT Stone guard	5874102170	1	13.27	0.2	0.0
55			Repi	LT Stone guard	5874202160	1	13.27	0.2	0.0
56	*	S01	Rpr	RT Quarter panel		0	0.00	<u>6.0</u>	2.4
57				Overlap Major Adj, Panel		0	0.00	0.0	-0.4
58				Add for Clear Coat		0	0.00	0.0	0.4
59	*	S01	Rpr	LT Quarter panel		0	0.00	<u>8.0</u>	2.4
				Note: see photos					
60				Overlap Major Adj. Panel		0	0.00	0.0	-0.4
61				Add for Clear Coat		0	0.00	0.0	0.4
62	*	501	Rpr	LT Tail lamp pocket		0	0.00	<u>4.0</u>	0.5
				Note: see photos. repair still cost effe	ctive with exception to ad	lditional re	pair time of inner :	structure	
63				Overlap Minor Panel		0	0.00	0.0	-0.2
64	*	S01	Rpr	RT Tail lamp pocket		0	0.00	<u>3.0</u>	0.5
65				Overlap Minor Panel		0	0.00	0.0	-0.2
66		S01	R&I	RT Upper qtr trim gray		0	0.00	0.2	0.0
67		S01	R&I	LT Upper qtr trim gray		0	0.00	0.2	0.0
68	BACK	GLASS							
69	*		Rpr	Back glass Toyota(rope)		0	0.00	<u>0.7</u>	0,0
70	*	S01	Sub	R&I Back glass Toyota(package tray access)		1	<u>71.50</u> X	0.0	0.0
71	**	S01	Repl	A/M Urethane Kit		1	21.45	0.0 G	0.0
72	REAR	DOOR							
73		<b>S</b> 02	Bind	RT Outer panel (HSS)		0	0.00	0.0	1.0
74		S02	Bind	LT Outer panel (HSS)		0	0.00	0.0	1.0
75		S02	R&I	RT Belt molding		0	0.00	0.3	0.0
76		S02	R&I	LT Belt molding		0	0.00	0.3	0.0
77		S02	R&I	RT Handle, outside slate gray		0	0.00	0.3	0.0
78		502	R&I	LT Handle, outside slate gray		0	0.00	0.3	0.0
7 <del>9</del>		S02	R&I	RT R&I trim panel		0	0.00	0.4	0.0
80		S02	R&I	LT R&I trim panel		0	0.00	0.4	0.0

Page 3

Supplement of	Record 4	with Summary
---------------	----------	--------------

29 A 1933 A 2014 A 2

Cust	omer:	тотн,	FRAI	NCIS				Job Nu	umber:
2015 T	'OYO Cor	olla LE w	/Contin	uously Variable Transmission 4D SED 4	1.8L Gasoline Sequential	MPI blueis	sh gr		
81	*	S02	R&I	RT Body side mldg		0	0.00	0.2	0.0
82	*	<b>S0</b> 2	R&I	LT Body side mldg		0	0.00	<u>0.2</u>	0.0
83	#	S02	Repl	Clean and retape body side molding		1	2.00	0.5	0.0
84	#	<b>S</b> 02	Repl	Clean and retape body side molding		1	2.00	0.5	0.0
85	PILLA	RS, ROO	KER 8	FLOOR			<ul> <li>a thread a transformed from a thread of the set</li> </ul>	the extended to the	
86			R&I	RT Rocker molding		0	0.00	0.4	0.0
87			R&I	LT Rocker molding		0	0.00	0.4	0.0
88	ROOF								
89			Repl	RT Drip molding	7555502210	1	50.57	0.3	0.0
90			R&I	LT Drip molding		0	0.00	0.3	0.0
91		501	Repl	RT Drip molding retainer clip	7556152040	2	2.76	0.0	0.0
92	WIND	SHIELD							
93	*		Rpr	Windshield Toyota(rope)		0	0.00	<u>0.7</u>	0.0
94	WHEE	LS		<ul> <li>A second control of the second</li></ul>			n ann an 1966 1977 - 1977 - 1986 1986 - 1986 1986 - 1986 1986 - 1986 1986 - 1986 1986 - 1986 1986 1986 1986 19	and a second of	1
95			R&I	Spare Wheel, spare		0	0.00	0.2	0.0
96	#			Hazardous Waste Disposal		1	5.00 T	0.0	0.0
97	#		Rpr	Tint Color to Match		0	0.00	0.5	0.0
98	#		Repl	Cover Car		1	5.00	0.2	0.0
99	**		Repl	A/M Flex Additive		1	5.00	0.0	0.0
100	**		Repl	A/M Corrosion Protection		1	15.00 T	0.0	0.0
101	EXHAL	JST SYS	TEM		nan a dan mus dha kad hashidd nga 🦷 a a a a				
102	*		R&I	Muffler & pipe w/o chrome tip		0	0.00 m	<u>0.4</u> M	0.0
103	FENDE	R							,,
104			R&I	RT Hinge cover		0	0.00	0.2	0.0
105			R&I	LT Hinge cover		0	0.00	0.2	0.0
106	#	501	Repl	8mm Drill bit		1	36.18	0.0	0.0
107	**	S01	Rep	A/M Fusor800		1	19.05	0.0	0.0
108	#	S03	Subl	Clear Door Edge Guard +25%		1	62.50 X	0,0	0.0
109	#	S03	Subl	Clear Dog Leg Guard +25%		1	62.50 X	0.0	0,0
110	#	S03	Subl	Finger Nail Guards +25%		1	25.00 X	0.0	0.0
					UBTOTALS		3,075.12	55.6	19.4

#### NOTES

Estimate Notes: LKQ :477738 8&R:3127007 PSC:35768

Prior Damage Notes: slight scratches on hood of vehicle.

Respondent 000004

# Supplement of Record 4 with Summary

#### **Customer: TOTH, FRANCIS**

and the second second second

#### Job Number:

2015 TOYO Corolla LE w/Continuously Variable Transmission 4D SED 4-1.8L Gasoline Sequential MPI blueish gr

#### **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				2,905.12
Body Labor	51.2 hrs	@	\$ 42.00 /hr	2,150,40
Paint Labor	19.4 hrs	@	\$ 42.00 /hr	814.80
Mechanical Labor	0.4 hrs	@	\$ 90.00 /hr	36.00
Frame Labor	4.0 hrs	@	\$ 42.00 /hr	168.00
Paint Supplies	19.4 hrs	@	\$ 28.00 /hr	543.20
Miscellaneous				170.00
Subtotal				6,787.52
Sales Tax	\$ 3,396.82	0	8.2500 %	280.24
Grand Total				7,067.76
Deductible				500.00
CUSTOMER PAY				500.00
INSURANCE PAY				6,567.76

Page 5